



Regulating throttle: Replacement now possible for Boxer, Daily, Ducato, Jumper

Vehicles:		Product: Regulating throttle (diesel)		
Cítroën, Fiat, Iveco, Peugeot		PIERBURG No.	Replacement for*	Ref. No.*
Fiat/Iveco	Daily V C15/Ducato 3.0 JTD	7.01754.10.0	7523D 7.01754.07.0	504105594; 504264089; 504345917; 71724299; 71724302
Peugeot	Boxer III 3.0HDi		163638	
Cítroën	Jumper 3.0 HDi			163671/163676

For the above mentioned diesel vehicles, from the start of serial production 04/2006 a regulating throttle with the reference number 7523D has been installed. During serial production (from 2009), this regulating throttle has been replaced by a PIERBURG regulating throttle.

The originally installed regulating throttle 7523D can no longer be supplied and could not be replaced as yet.

With the adapter cable 4.07360.49.0, this regulating throttle can now be replaced by the PIERBURG regulating throttle 7.01754.10.0.



Product view 7.01754.10.0 (gasket included in scope of delivery)

Note when ordering:
 If the installed regulating throttle 7523D is replaced by the PIERBURG regulating throttle 7.01754.10.0, the adapter cable 4.07360.49.0 is required.



Adapter cable 4.07360.49.0

The right of changes and deviating pictures is reserved. For assignment and replacement parts, refer to the current catalogues, TecDoc CD or respective systems based on TecDoc.

* The reference numbers given are for comparison purposes only and must not be used on invoices to the consumer.